



**FOR PRICE LISTING
GO TO PAGE 317**



PLASMA CUTTING

Replacement Parts

ACCESSORIES Suitable For

ESAB® (L-TEC® / Linde®)

Torch Model	Power Supply Model
PT-17A / PT-17AM	PCM-150 (875 / 1125 W/ADAPTER)




REQUIREMENTS:
 Gas: Air
 Pressure: 75 psi
 Flow: 4.8 scfm

ACCESSORIES Suitable For

ESAB® (L-TEC® / Linde®)

Torch Model	Power Supply Model
PT-19XL	ESP-200, PCM-150, DEUCE-11, DEUCE PACK 150



ADDITIONAL ITEMS NOT SHOWN

T-1427 Nozzle, Bevel, O ₂	T-1254 O-Ring
T-1426 Nozzle, Bevel, O ₂ , CCW	T-1255 O-Ring
T-1247 Locating Pin	T-1256 O-Ring
PX34885 Heat Shield, 50A	T-1257 O-Ring
PX999630 Nozzle removal tool	PX34730 Nozzle Ass'y, 50A

ACCESSORIES Suitable For

ESAB® (L-TEC® / Linde®)

Torch Model	Power Supply Model
PT-17A / PT-17AM	PCM-8, ESP-1000



Leads Complete

T-1218 Hand Leads, 25'	T-1220 Machine Leads, 25'
T-1219 Hand Leads, 50'	T-1221 Machine Leads, 50'




Torch w/Leads – Not Shown

T-1222 Hand Torch w/25' Leads	T-1223 Machine Torch w/25' Leads
T-1224 Hand Torch w/50' Leads	T-1225 Machine Torch w/50' Leads

ACCESSORIES Suitable For

ESAB® (L-TEC® / Linde®)

Torch Model	Power Supply Model
PT-19XL	



Stoody Industrial & Welding Supply, Inc. (SIWS) is not associated with STOODY Company or any of the above manufacturers. SIWS reserves the right to substitute OEM products in place of parts shown.