



FOR PRICE LISTING
GO TO PAGE 317


PLASMA CUTTING

Replacement Parts

ACCESSORIES Suitable For


ESAB® (L-TEC® / Linde®)

Torch Model	Power Supply Model
PT-31, PT-31XL & XT	PCM-500/875/1125/SMI



Leads Assembly

T-1191 Leads Assy 12.5'	T-1192 Leads Assy 25'
T-1193 Leads Assy 50'	



ITEM NOT SHOWN


Hand Torch	Machine Torch
T-1194 w/ 12.5' Leads	T-1197 w/ 12.5' Leads
T-1195 w/ 25' Leads	T-1198 w/ 25' Leads
T-1196 w/ 50' Leads	T-1199 w/ 50' Leads

XL, XT and Standard Parts Should Not Be Mixed When Cutting

Suitable For

ESAB® (L-TEC® / Linde®)


Torch Model	Power Supply Model
PT-32	875, 1125, 1500



Suitable For

ESAB® (L-TEC® / Linde®)


Torch Model	Power Supply Model
PT-34	HP125



Suitable For

ESAB® (L-TEC® / Linde®)


Torch Model	Power Supply Model
PT-121	PCM-150



ACCESSORIES Suitable For


ESAB® (L-TEC® / Linde®)

Torch Model	Power Supply Model
PT-121	PCM-150



Leads Assembly

T-1241 Hand Leads, 25'	T-1243 Machine Leads, 25'
T-1242 Hand Leads, 50'	T-1244 Machine Leads, 50'



Stoody Industrial & Welding Supply, Inc. (SIWS) is not associated with STOODY Company or any of the above manufacturers. SIWS reserves the right to substitute OEM products in place of parts shown.