

EXOTHERMIC CUTTING INFORMATION

SLICE TORCHES / STRIKERS / KITS

TORCH PARTS AND CUTTING RODS



Scan for
Current Price Page

SLICE TORCHES / STRIKERS / KITS



TORCH FOR USE WITH AN ARC WELDER

INCLUDES: TORCH
10' CABLE W/ LUG
10' OXYGEN HOSE W/ (B) STYLE NUT
\$762.86 EA
Part No. 03-003-000

OPTIONAL SLICE® STRIKER

This optional SLICE® Striker provides a convenient surface for igniting the rod with a 12-volt battery instead of a welding power supply.



\$236.00 EA

Part No. 72-012-002

NOTE: STRIKER COMES STANDARD WITH A MALE CAM-LOK PLUG, ORDER SPRING TYPE ELECTRICAL CLAMP IF YOU PLAN TO CLAMP DIRECTLY INTO A BATTERY

SLICE torch can use 1/4" & 3/8" diameter of cutting rods by simply changing the collet nut and collet chuck

Comfortable and easy to use pistol grip design handle

Lightweight shield to help protect the operator from heat and sparks

Easy to squeeze lever on the handle for easy oxygen control

Arcair.

KIT FOR USE WITH AN EXISTING STANDARD 12 VOLT BATTERY

The SLICE® Utility Pack permits you to use the exothermic cutting process to cut virtually any metallic, non-metallic or composite material. This package has the basic items needed to do a cutting job packed in a rugged toolbox. Just supply oxygen and an ignition source and you are ready to cut.

The power cables on the torch and striker assemblies in this pack should be used with a 12-volt battery only. Also included is a collet extension and shield for added protection when piercing. The following items are included in the SLICE Utility Pack:

DESCRIPTION

SLICE Utility Pack
Tool Box
Torch Assembly
Striker Assembly
Collet Extension Assembly
Extension Shield
Clamp (Red)
Clamp (Black) Coupling
Instruction Manual



SLICE® UTILITY PACK

Part No. 63-991-026

\$1,022.21 EA