



REPLACEMENT – CUTTING & WELDING TIPS


SUITABLE FOR NCG TORCHWELD REGO / REXARC

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER		
	Acetylene - Oxygen	6 preheats	62....	200263-28		
			56....	200257-28		
			53....	200253-28		
			51....	200251-28		
			46....	200246-28		
			42....	200242-28		
			35....	200235-28		
			30....	200230-28		
			\$26.80 EA			


Medium preheat. For general cutting operations.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Fuel Gas - Oxygen	KX-105	68....	202768-28
			62....	202762-28
			56....	202756-28
			53....	202753-28
			51....	202751-28
			46....	202746-28
			42....	202742-28
			35....	202735-28
			30....	202730-28
			25....	202725-28
ALL SIZES \$26.00 EA				


Two piece, general purpose cutting tip for use with propane (or other fuel gases) and oxygen.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER		
	Fuel Gas - Oxygen	KX-205	75....	203014-28		
			72....	203012-28		
			68....	203010-28		
			60....	203008-28		
			53....	203006-28		
			46....	203004-28		
			35....	203002-28		
			ALL SIZES \$28.50 EA			


Two-piece, High-speed tip. For machine cutting.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Acetylene - Oxygen	KXMC	72....	202872-28
			68....	202868-28
			60....	202860-28
			53....	202853-28
			46....	202846-28
			35....	202835-28
ALL SIZES OBSOLETE				


Medium preheat, divergent nozzle cutting tip. For high speed cutting.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Acetylene-Oxygen (150P)	NCG 150 For No. 48 Attachment	65....	201365-27
			62....	201362-27
			56....	201356-27
			53....	201353-27
			ALL SIZES \$28.50 EA	


Medium preheat, hand cutting light plate. Very small tip used with cutting attachment.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Lead Burning with Natural Gas Light Welding with Acetylene	NCG 170 Tips Only	79....	190479-27
			76....	190476-27
			72....	190472-27
			68....	190468-27
			62....	190462-27
			58....	190458-27
			55....	190455-27
			53....	190453-27
			50....	190450-27
			46....	190446-27
			42....	190442-27
			ALL SIZES OBSOLETE	


Bent elbow copper tip only.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Acetylene - Oxygen	GXU Swage Tips Only No mixers	62....	180462-28
			50....	180450-28
			46....	180446-28
			42....	180442-28
			ALL SIZES \$22.00 EA	


Bent elbow copper tip only.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Fuel Gas - Oxygen	233	68....	200612-27
			62....	200611-27
			56....	200610-27
			53....	200609-27
			51....	200608-27
			46....	200607-27
			42....	200606-27
			35....	200605-27
			30....	200604-27
			25....	200603-27
ALL SIZES OBSOLETE				


Two-piece tip for hand and machine cutting. Medium preheat.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Fuel Gas - Oxygen	243	68....	204312-27
			62....	204311-27
			56....	204310-27
			53....	204309-27
			51....	204308-27
			46....	204307-27
			42....	204306-27
			35....	204305-27
			30....	204304-27
			25....	204303-27
ALL SIZES OBSOLETE				


Two-piece general purpose cutting tip. Medium range.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Acetylene - Oxygen	247	68....	204710-27
			62....	204709-27
			56....	204708-27
			53....	204707-27
			51....	204706-27
			46....	204705-27
			42....	204704-27
			35....	204703-27
			30....	204702-27
			25....	204701-27
ALL SIZES OBSOLETE				

One-piece general purpose cutting tip. Medium preheat.


SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Acetylene - Oxygen	250	68....	200068-27
			62....	200062-27
			56....	200056-27
			53....	200053-27
			51....	200051-27
			46....	200046-27
			42....	200042-27
			35....	200035-27
			30....	200030-27
			25....	200025-27
18....	200018-27			
ALL SIZES OBSOLETE				

General hand and scrap cutting. Medium preheat.


SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Fuel Gas - Oxygen	343	75....	203134-28
			72....	203132-28
			68....	203130-28
			60....	203128-28
			53....	203126-28
			46....	203124-28
35....	203122-28			
ALL SIZES OBSOLETE				

Two-piece. For high speed machine cutting with propane or natural gas.


SUITABLE FOR SMITH - OLD STYLE

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Acetylene - Oxygen	LC-4	0.....	LC0-4
			1.....	LC1-4
			2.....	LC2-4
			3.....	LC3-4
			4.....	LC4-4
ALL SIZES OBSOLETE				

Light preheat. For general cutting operations. Use LC-6 Series

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Acetylene - Oxygen	LC-6	0.....	LC0-6
			1.....	LC1-6
			2.....	LC2-6
			3.....	LC3-6
			4.....	LC4-6
			5.....	LC5-6
6.....	LC6-6			
ALL SIZES \$40.00 EA				

Heavy preheat. For general cutting operations. High speeds.

SKETCH & DESCRIPTION	FUEL	TIP STYLE	SIZES	PART NUMBER
	Propane - Oxygen	LC-46 Propane	1.....	LC31-0
			2.....	LC32-0
			3.....	LC33-0
			4.....	LC34-0
			5.....	LC35-0
			6.....	LC36-0
ALL SIZES \$45.00 EA				

Two-piece type for general cutting of steel. Propane must be delivered at a minimum of 5 psi. Heavy preheat.

UNIWELD CUTTING/WELDING/HEATING TIPS

TORCH TYPE

"A"
"H"
"V"

USE

"A" STYLE TIP
"H" STYLE TIPS
"V" STYLE TIPS